

**Biomet3i™ Implant Recall (4/11)**

Biomet recently initiated a voluntary recall on Biomet 3i™ implants (Lot # 963841, INT 411, Osseotite® NT Tapered® Certain Implant, 4 mm x 11.5 mm and Lot # 2009110838, IOSS 413, Osseotite® Certain Implant, 4mm x 13 mm). The company is taking this action due to a condition affecting the internal thread of the implant. If present, the condition will be immediately recognizable as it will prevent the cover screw, temporary healing abutment, and final restorative abutment from engaging the implant. If you ordered the following defective implants you should have been notified by Biomet already, if you have not been notified please check your inventory for either of the lot numbers listed above and return the unused implants to Biomet 3i for replacement:

BIOMET 3i  
Regulatory Compliance Department  
4555 Riverside Drive  
Palm Beach Gardens FL 33410

If you have additional questions about this recall, please contact Biomet Recall Coordinator Mark Mashburn at (561) 776-6906.