

Test Strips in Dry Heat Sterilizer Operations Alert (7/16)

Reason/Information:

CROSSTEX Issued a Voluntary Market Alert Notice on the following materiel. **Reason:** CROSSTEX received reports where test strips glassine is peeling and or falling apart during Dry Heat sterilizer operations.

Disposition/Instructions:

Actions to be taken:

--CROSSTEX recommends the test strips be held in place with a clip per your sterilizer's operation manual.

If customers have questions regarding this notification, contact the QA department at Comm: 558-359-0130 or email at josev@crosstex.com.

Additional information and documentation can be found by clicking [here](#).