

**Sybron Endo Lightspeed: LSX File RECALL (3/13)**

Ormco/Sybronendo and the FDA have issued a voluntary recall on certain parts and lots of Sybron Endo Lightspeed: LSX Files due to the 'length markings on the Lightspeed LSX files were wrong'. Lightspeed: LSX files are an engine-driven rotary endodontic instrument used during endodontic procedures for cleaning and shaping the root canal. The affected part and lot numbers are listed below:

Part # 835-2525, Lot # 091274189.

Part # 835-2455, Lot # 091272054, 091279295, 101200609, 101200610, 101200612.

Part # 835-2031, Lot # 091268204

For more information click on the below link to the FDA:

[http://www.accessdata.fda.gov/scripts/enforcement/enforce\\_rpt-Product-Tabs.cfm?action=select&recall\\_number=Z-0765-2013&w=02132013&lang=eng](http://www.accessdata.fda.gov/scripts/enforcement/enforce_rpt-Product-Tabs.cfm?action=select&recall_number=Z-0765-2013&w=02132013&lang=eng)

or Contact Sybronendo Customer Service at 1-800-346-3636 if you have any of the affected lots.